MASTECH[®]

M300C

POCKET-SIZEDDIGITAL MULTIMETER OPERATOR'S INSTRUCTION MANUAL









MASTECH[®]

Safety information

This meter has been designed according to EN61010-1, EN61010-2-030, EN61010-2-033, 300V CAT III and pollution2.

Follow all safety and operating instructions to ensure the meter is used safely and is kept in good condition With proper use and care, your digital multimeter will give you years of satisfactory service.

During use

- Never exceed the protection limit indicated in the specifications for each range of measurement.
- Never use the meter to measure voltages that might exceed 300V above earth ground in category III installations
- Always be careful when working with voltages above 60v dc or 30v ac rms. keep fingers behind the probe barriers while measuring.
- Do not perform resistance measurements on live circuits.
- Inspect test leads and probes for cracks, breaks or crazes in the insulation before using the meter
- If the equipment is used in a manner not specified by manufacturer, the protection provided by equipment may be impaired.

Safety Symbols

Important safety information ,refer to the instruction manual. Earth(ground) TERMINAL		Important safety information ,refer to the instruction manual.
		Earth(ground) TERMINAL

MASTECH[®]


	Equipment protected throughout by double insulation.	
+	Fuse must be replaced with ratings specified in the manual.	
~	AC (Alternating Current)	
===	DC (Direct Current)	
It is applicable to test and measuring circuits connected to the distribution part of the build low-voltage MAINS installation.		
(€	European union directives	
c us	CONFORMS TO UL STD. 61010-1, 61010-2-030, 61010-2-033, 61010-031; CERTIFIED TO CSA STD. C22.2 No.61010-1,61010-2-030, 61010-2-033, 61010-031.	

Maintenance

- Before opening case .always disconnect test leads from all energized circuits.
- For continuous protection against fire. Replace fuse only with ratings: F 250mA/300V (Quick Acting)
- Never use the meter unless the back cover is in place and fastened completely.
- Do not use abrasives or solvents on the meter .to clean it use only a damp cloth and mild detergent.

MASTECH[®]

FRONT PANEL



Range switch

This switch is used to select desired ranges as well as to turn on/off the meter .

2. Function switch switch for selecting functions.

LCD display

3 1/2digit.7segment.maximum 1999 counts.

4. Test leads

Red test lead for positive (+) and black test lead for negative (-).

MASTECH[®]

General description

This compact digital multimeter is designed to measure AC and DC voltages .DC current .Resistance Diode and to perform audible continuity checks with accuracy and easy .

Small and lightweight .with a carrying case and test leads wound on its body. This instrument will provide you years of satisfactory service.

Specification

Accuracy is guaranteed for 1 year . 23°C ±5°C. Less than 75%RH.

DC Voltage

Range	Resolution	Accuracy
2V	1mV	±0.5% of rdg ±1dgt
20V	10mV	±0.8% of rdg ±1dgt
200mV	100mV	±0.8% of rdg ±1dgt
300V	1V	±0.8% of rdg ±1dgt

Overload protection:300V dc or rms ac for all ranges

AC Voltage

Range	Resolution	Accuracy
200V	100mV	±1.2% of rdg ±10dgts
300V	1V	±1.2% of rdg ±10dgts

Overload protection: 300V dc or rms ac for all ranges Frequency range: 45Hz to 450Hz

Response: average responding .calibrated in rms of a sine wave

01 02 03 04

MASTECH

DC Current

Range	Resolution	Accuracy
200mA	0.1mA	±2.0% of rdg ±2dgts

Overload protection: 250mA/300V fuse

Resistance

Range	Resolution	Accuracy
2kΩ	1Ω	±1.0% of rdg ±2dgts
20kΩ	10Ω	±1.0% of rdg ±2dgts
200kΩ	100Ω	±1.0% of rdg ±2dgts
2000kΩ	1kΩ	±1.0% of rdg ±2dgts

Maximum open circuit voltage: 0.65V overload protection: 250V rms ac for all ranges

Diode test

Range	ange Description	
*	Show the approx. forward voltage drop of the diode.	

Overload protection: 250V rms ac

Diode test

Range	Description	
01)	Built-in buzzer sounds when resistance is less than 50Ω.	

Overload protection: 250V rms ac

MASTECH[®]

General characteristics

CAT III 300V
F 250 mA/300V
12V battery .GP -23AX1
LCD .1999 counts .updates 2-3/sec
dual-slope integration A/D converter
only figure "1" on the display
" - " displayed for negative polarity
0°C to 40°C (32°F to 104 °F)
-10°C to 50°C (10°F to 122°F)
appears on the display
120x70x18mm
approx.110g

Operating instruction

DC Voltage measurement

- 1. Set the function switch at V = position
- 2.Set the range switch at desired position. If the magnitude of voltage to be measured is unknown beforehand. set the range switch at the highest position and then reduce until satisfactory reading is obtained.
- 3.Connect test leads across the source or load being measured. The polarity of red lead connection will be indicated at the same time as the voltage value.
- 4. When the range switch is set at 300V position. "HV" sign will appear on the display to remind user of high voltage measurement. Special attention should be paid.

MASTECH[®]

AC Voltage measurement

- 1. Set the function switch at V~ position
- Set the range switch at desired position .measurement reading can be obtained at 2V and 20V positions, but the accuracy is not guaranteed.
- Connect test leads across the source or load being measured and read the voltage value on the LCD display.
- When the range switch is set at 300V position, a "HV" sign will appear on the display to remind user of high voltage measurement.

DC Current measurement

- 1. Set the function switch at A position.
- Set the range switch at 200mA position .measurement reading can be obtained at other positions. But the decimal point will be at the incorrect place.
- Open the circuit in which the current is to be measured.
 And connect test leads in series with the circuit.
- 4. Read current value on the LCD display along with the polarity of red lead connection.

Resistance measurement

- 1. Set the function switch at Ω position .(note: the polarity of red lead is positive "+")
- 2. Set the range switch at desired position
- 3. Connect test leads across the resistor to be measured and read LCD display.
- If the resistor was being measured is connected to a circuit .turn off power and discharges all capacitors before applying test leads.

MASTECH[®]

Diode test

- 1. Set the function switch at Ω position .(note: the polarity of red lead is positive "+")
- 2. Set the range switch at → position.
- 3. Connect the red test lead to the anode of the diode to be tested and the black lead to the cathode of the diode.
- 4. The approx. forward voltage drop of the diode will be displayed in mv.if the connection is reversed. Only figure "1" will be shown

Audible continuity test

- 1. Set the function switch at Ω position.
- 2. Set the range at ••) position.
- 3. Connect test leads to two points of the circuit to be tested if the resistance is less than 50Ω. Buzzer will sound.

Battery & Fuse Replacement

If the sign appears on the LCD display .it indicates that the battery should be replaced. Remove the screw on the back cover and open the case .replace the exhausted battery with a new one of the same type.

Fuse rarely need replacement and blow almost always as a result of operator's error. open the case and replace the blown fuse with the ratings specified: F 250 mA/300V.

△WARNING

To avoid electric shock, make sure the probes are disconnected from the measured circuit before removing the rear cover. Make sure the rear cover is tightly screwed before using the instrument.

MASTECH[®]

Replacing test leads

Replace test leads if leads become damaged or worn.

△WARNING

If the test leads need to be replaced, you must use a new one which should meet EN 61010-031 standard, rated CAT III 300V. 0.4A or better.

Warning

Before attempting to open the case .always be sure that test leads have been disconnected form measurement circuits. close case and tighten screws completely before using the meter to avoid electrical shock hazard

Accessories

1pcs (12V GP-23A)
1pcs
1pcs



 05
 06
 07
 08
 00-05-4065